

# Prime Guard Filters

## Sales and Marketing Bulletin

**Bulletin Number: PG17-03-17**

**March 17, 2017**

**CUSTOMER:** Prime Guard Filter Customers

**SUBJECT:** POF5839 Prime Guard Cartridge Oil Filter  
GM 1.4L – 1.8L Engine Oil Cartridge – Vehicles with Hengst® or UFI® Oil filter Adapters

**FROM:** Prime Guard Technical Service Department

### Important Service Update:

GM Vehicles with 1.4L-1.8L engines may come from the factory with one of two oil filter adapters (OFA). These two adapters are almost identical in outward appearance with the exception of the vendor name on the cast aluminum housings and the injection molded nylon caps. They **DO NOT** use the same cartridge filters. See Photos below.



**Hengst Housing and Filter Cartridge**



**UFI Housing and Filter Cartridge**

**NOTE:** The filters for the different oil filter housings are not interchangeable and if incorrectly used may lead to serious engine damage.

The Hengst® housing is equipped with a bypass valve located in the housing's post. Prime Guard recommends the POF5839 oil filter for this application

The UFI® housing is not equipped with a bypass valve. The bypass valve is located in the oil filter. Prime Guard recommend the POF9177 for this application. Note: The POF9177 is currently under development. In the interim, the ACDelco PF2263G is available from Prime Guard.

### Vehicles Affected Include (but are not limited to):

Year	Make	Model	Engine
2013-2017	Buick	Encore	1.4L
2013-2017	Chevrolet	Sonic	1.4L
2013-2017	Chevrolet	Sonic	1.6L*
2013-2017	Chevrolet	Sonic	1.8L
2013-2017	Chevrolet	Trax	1.4L
2013-2017	Chevrolet	Trax	1.8L
2015-2016	Chevrolet	Cruze	1.4L
2015-2016	Chevrolet	Cruze	1.8L

\* Non-Canada and U.S.

Please contact your salesperson with any questions or concerns you may have.

Prime Guard Technical Service Department